
2. Defect Photos and Details

2.1 B2 parking lot

B2 parking lot-1

Location	B2 parking lot
Surface	Floor
Photo no.	1
Captured (KST)	2026-06-18 16:45:05 KST
Defect type	Crack
Crack width ≥ 0.3 mm	0
Expected repair method	Epoxy injection
Crack length (m)	11.77
Max crack width (mm)	14.09
Total repair area (m ²)	2.80

Analysis result

